

FIG. 2




FIG. 3




FIG. 4





FIG. 5



Six Measurements Obtained

$F_{\text{high}}$  High  
 $F_{\text{low}}$  Low  
 $F_{\text{b}}(\text{high})$   
 $F_{\text{b}}(\text{low})$

FIG 6

$$F_{\text{high}} = F_{\text{a}}(\text{high})/F_{\text{b}}(\text{high})$$

$$F_{\text{low}} = F_{\text{a}}(\text{low})/F_{\text{b}}(\text{low})$$

$$t^* = [\ln(F_{\text{high}}) - \ln(F_{\text{low}})]/(F_{\text{high}} - F_{\text{low}})$$

FIG 7

MAP OF FRACTURED ZONE






FIG 8



BEST AVAILABLE COPY




Fig 11

O P I P E J C A S  
JUN 24 2003  
PATENT & TRADEMARK OFFICE

BEST AVAILABLE COPY




FIG. 11